



2023-004 Lead Abatement 171 Sixth Street

8/10/2022

Room #	Building Component	Location	Abatement Method	Sanderson Painting			Ray Corp			Kennebec Abtmnt			TWPro			RCGroup		
				Labor	Materials	Total	Labor	Materials	Total	Labor	Materials	Total	Labor	Materials	Total	Labor	Materials	Total
Ext	Door Overhang Fascia	A4	SPP Encapsulate	400	100	500	1200	600	1800						1200	1200	400	1600
Ext	Door Case	C3	Coil Stock Enclosure	400	100	500						0	0	0	600	200	800	
Ext	Door Jamb	C3	Scrape to Bare	200	0	200	500	300	800			0	0	300	200	500		
Ext	Fascia	ABCD	Coil Stock Enclosure	800	200	1000	2200	800	3000			2600	2475	3000	1000	4000		
Ext	Basement Wndw Sash	C6D6D7	remove Replace	1200	600	1800	1000	800	1800			2100	4500	900	800	1700		
Ext	B-Wndw Sill	C6D6D7	Coil Stock Enclosure	300	100	400	700	300	1000			1000	1550	1800	900	2700		
Porch #4	Upper Wall Header	BCD	SPP / encapsulate	800	200	1000	500	300	800			1500	1575	1600	400	2000		
Porch #4	Lower Wall Sill / Shelf	BCD	SPP / encapsulate Add trim board	400	100	500	500	300	800			1500	1225	900	400	1300		
<b>Total</b>				<b>\$5,900.00</b>			<b>\$10,000.00</b>			<b>\$12,000.00</b>			<b>\$12,525.00</b>			<b>\$14,600.00</b>		